

A Clean Sweep Limited use the most advanced and accurate camera systems to diagnose y  
In order to locate issues, infrared CCTV cameras are passed up and down the flue to give a high



### **This enables us to:**

- View blocked flues or restricted flues caused by animal nests, fallen debris, restricted bends or other objects breaching the flue
- Identify the flues dimensions and confirm the most appropriate lining method
- Establish the cause of a major smoke leakage
- Check for damage which may have occurred following chimney fires, subsidence or wear and tear over time

**Our highly advanced CCTV equipment diagnoses the problem quickly and effectively without any disruption to you or your building.**

**[For more information call us on 01932 798 014](tel:01932798014)**